

THREE PHASE with OVERLOAD with TIME METER



MADE IN ITALY

THREE PHASE WITH OVERLOAD WITH TIME METER

BX16HETH1 1-way, 1/4, ON-OFF reset button
max work pressure 12 bar (on demand 16 bar)
20 Amp. - 50/60 Hz - dim. 100x120x135 - 850 gr. weight
Amp. range: 2,5-4 / 4-6,3 / 6,3-10 / 10-16 / 13-18 / 16-20 / 17-23

BX16HETH4 4-ways, 1/4 , ON-OFF reset button
max work pressure 12 bar (on demand 16 bar)
20 Amp. - 50/60 Hz - dim. 100x120x135 - 850 gr. weight
Amp. range: 2,5-4 / 4-6,3 / 6,3-10 / 10-16 / 13-18 / 16-20 / 17-23